


STACINE









DURING ASSEMBLY CHECK AND TIGHTEN ALL BOLTS

A	\	() () () () () () () () () () () () () (4 PCS	D	M8X35	2 PCS	G	(humana) M 6 X 2 5	4 PCS
E	3		2 PCS	Ш	M8X65	2 PCS	Н		1SET
C	;	()∭ () () () () () () () () () () () () () ()	2 PCS	F		1PC			

